

HELP: 1-888-751-4086 (Tech Support)

GSPN

http://gspn3.samsungcsportal.com

PLUS ONE

http://my.plus1solutions.net/clientPortals/samsung

HOT TIPS

Power On Problems: (see page 2) Video Problems: (see pages 3,4) TIP: After replacing Main/Panel picture is upside down.

Fix: Test Mode/Mirror Option/Toggle

FIRMWARE

2/21/2011

Firmware for Valencia 1G Model Version:
1035.0 Folder Name: T-VALAUSC
Support Netflix 2.1 and MLB.tv apps.
Add "3D Optimize" option on Menu for better 3D image.(Only LCD/LED TV)
And this firmware prevents below issues

- . 'USB Power Overload' message pops up even USB port is not connected
- . HDMI ports recognition error and signal loose
- . Plug & Play is displayed whenever turning on TV.

SERVICE BULLETINS

6/20/11 Issues will be apparent if options bytes are not set

ASC20110620001

<u>Version</u>		
	<u>Parts No</u>	Short Description
ALL	BN44-00340B	Power PCB
		Function & IR PCB
ALL	BN96-13226B	
ALL	BN94-02620L	Main PCB
ALL	BN07-00831A	Panel
ALL	BN81-04412A	T-CON PCB
ALL	BN96-10689A	Stand Guide Neck
ALL	BN96-12767B	Rear Cover
ALL	BN96-13556C	Front Cover
ALL	BN96-12795C	Stand Guide
ALL	BN96-12762F	Stand Base
ALL	BN40-00163A	Tuner
ALL	BN96-12837A	Speaker
ALL	BN96-12723C	LVDS Cable
ALL	3903-000467	Power Cord
ALL	BN59-01076A	Remote
ALL	BN63-01798B	Cleaning Cloth



GND

GND

H_OUT

B13V_PW


OUT

B13V PW

B5V PW

B13V_PW

IP DET



Power On Sequence (approximate Voltages)

- **Standby Voltages: CN201-4 (5V)**
- Power On CN201-2 (0 3V)
- **Low Voltage Supplies On CN201-**3. 1,3,5,7,13,15,17 (Volts Listed on CN802)
- Back Light On CN201-16 (0-3V, delayed)
- **Back Light Confirm CNI802- (FB1 & FB2)** 5.
- 6. Dimming Signal CN201-14 (1V-4V approx)

To Force Backlight On without Main Board:

- Remove Power Cord
- 2. Remove CN802
- 3. Plug Power Cord In.
- Backlight should be on immediately.

CN401(to Function/IR)				
1	IR 6 KEY_INP		KEY_INPUT1	
2	GND	7	KEY_INPUT2	
3	A3.3V_PW	8	LED_STB	
4	MSCL_A5V	9	LED_CNTR	
5	MSDA_A5V	10	A3.3V_PW	

Fast Track Troubleshooting Manual

TROUBLESHOOTING VIDEO PROBLEMS

1. Verify Video Operation

- a. Customer Picture Test (models available)
- b. "Display" (If display is OK source is suspected)
- C. Substitute with known good Source (external DVD or Signal Generator)

2. Using Test Patterns in Service Mode

- ENTER SERVICE MODE -

1. Select an active source signal. (HDMI preferred) Test Pattern may rely on signal source to appear.

Customer Remote

2.

Picture

Power off

Mute, 182, Power


2. Power On

Service Remote

3. Info, Factory

2010 Models with FRC 120Hz/240Hz


LCD Signal Path for Troubleshooting




3. Activate FBE Test Patterns & Verify.

4. Activate FRC Test Patterns & Verify.

T-Con Troubleshooting





SAMSUNG

Fast Track Troubleshooting Manual

ON SCREEN FAILURE EXAMPLES:



If Picture & Display errors Defective Main Board, LVDS, or T-CON




Green lines or a green screen defective main board, LVDS, or T-CON.



Original Image

Image on Screen

Pixelization can be caused by the main board but is more commonly a source error



Vertical or Horizontal Lines: Defective Panel likely but also T-CON, LVDS, or Main Board. Use Test Patterns in Factory Service Mode to determine error)

ALIGNMENTS:

1. Check/Set Option Bytes:

iss the remote buttons in this order; POWER OFF-MUTE-1-9-2-POWER ON to turn the set on. The set turns on and enters service mode. This may take approximately 20 seconds.

Initial SERVICE MODE DISPLAY State

Project Model Model Code		PB5G	PB5G	PB5G B550 PN63B550T2FXZA	
		B550	B550		
		PN50B550T2FXZA	PN58B550T2FXZA		
	ITEMS				
1	Factory Reset				
2	Type	50FSpL4	58FNfK1	63FMeK1	
3	Model	PB550	PB550	PB550	
4	TUNER	ALPS	ALPS	ALPS	
5	Region	US	US	US	
6	DDR	SAMSUNG	SAMSUNG	SAMSUNG	
7	Light Effect	Off	Off	Off	
8	Inch	50"	58"	63*	
0	F 4 7 10 - 14 - 1	0#	OW	0.00	

Option Bytes

Factory Reset				
Туре	50HShB4			
Model	P8550			
TUNER	ALPS			
Region	US			
DDR	SAMSUNG			
Light Effect	Off			
Inch	50"			
Exhibition Mode	Off			

SAMSUNG

Model Code	Front Color						
		Туре	Model	Tuner	Region	Side Label	
LN40C670M1FXZ A	T-C- BLK	40L1UF0C	LC670	Semco	US	AA03	

- 2. Check/Perform Firmware Upgrade for all repairs.
- 3. Perform reset in Service Mode & Plug and Play if Main board is replaced.

SPECIAL NOTES:

Inform customer of reset of all Settings if Main Board or Panel is replaced.